
Guide to Utility Marks

- Underground facilities shall be marked using the current color codes. (see chart below)
- The type of facility shall be noted by appropriate letter designation with at least three (3) markings at no more than 25ft intervals.
- Off-set marks may be used when there is a likelihood that the markings may be destroyed if placed directly over the facilities.
- To avoid placing paint, 8" whiskers may be used on decorated gravel, stone, or pavers.

COLOR CODE CHART FOR MARKING UNDERGROUND UTILITY LINES



Steps to Take in the Event of a Damage

- Any damage caused or discovered to natural gas, liquid petroleum, or any hazardous liquid facilities, underground facilities, must be immediately reported to 911 in addition to the facility operator.
- All other damages are to be reported to the facility operator and New Jersey One Call Center at 811 or 1-800-272-1000.
- Take care not to damage the protective coating or tracer wire of any facility.
 If you do, leave the damaged facility exposed and contact the facility operator.
- You should keep emergency contact information of the facility operators on hand.
- If you do not know who owns the facility, call New Jersey One Call and they will send a message to the facility operators.

Damages to Natural Gas, Liquid Petroleum, or Hazardous Liquid Facilities:

- Call 911 immediately
- · Call the facility operator immediately thereafter to report the damage
- Call the New Jersey One Call Center at 811 or 1-800-272-1000.
- . Stop all work and evacuate the site
- · Do not create a spark or ignition source.
- Keep the public and traffic away.
- Tape, rope, or secure the area.
- · Stay upwind of blowing gas.
- Do not try to fix the damaged facility
- Do not attempt to extinguish a natural gas fire unless it is an immediate hazard to life; you may cause an explosion.

811

CALL FOR A FREE MARKOUT!

811 or 1-800-272-1000